



**CONSTRUCTION UPDATES & ACTIVITIES**

*Week Ending of July 7, 2017*

**San Luis Obispo Instructional Building**

**Work this week:** The electrical contractor has begun to install their cable tray within the first floor ceiling and is continuing with their second floor rough in. The plumbing and mechanical contractor is installing seismic bracing on their equipment throughout the building. Drywall installation is progressing on the second floor while the mechanical contractor is installing the air conditioning units that were hoisted to the roof last week.

- Noise:** Some noise
- Parking:** Some permanent parking loss
- Utilities:** None
- Odors:** None
- Dust:** Moderate dust impact
- Vibrations:** Minor vibrations
- Vision:** None

